COST ESTIMATE 60% Design							
Rogue Brewery Seawall Repair				Lincoln County			
	DESCRIPTION OF WORK Seawall Repair			DESIGNER			
Reference	ITEM DESCRIPTION	UNIT	AMOUNT	UNIT COST	SUBTOTAL		TOTAL
	FION, SURVEYING, CLEANUP, AND DEMOBILIZATION	UNIT	AWOUNT	UNIT COST	\$152,494.72	<u> </u>	TOTAL
WODILIZA	Mobilization and demobilization	L.S.	1	\$ 152,495	\$132,434.72	Ś	152,494.72
TEMPODA	RY RELOCATION OF THE FLOATING DOCK	L.S.	1	\$ 152,495	\$15.400.00	Ş	152,494.72
LIVIFORA	Removal of guide piles and relocation of floating docks	S.F.	550	\$ 28	ψ13, <del>4</del> 00.00	Ś	15,400.00
REPAIR OF	F PILE CAP CONCRETE SPALLING	э.г.	330	7 20	\$10,800.00	Ş	13,400.00
KLFAIK OI	Material + Labor	S.F.	20	\$ 540	\$ 10,000.00	Ś	10,800.00
DII E SLIRE	ACE PREPARATION AND COATING APPLICATION	5.1 .	20	ÿ J <del>-</del> 0	\$15.747.20	۲	10,000.00
FILL SUKI	Pile corrosion coating	S.F.	829	\$ 4.00	913,747.20	\$	3.315.20
	Pile surface preparation	S.F.	829	•		\$	12,432.00
WEEP HOLE DRAINAGE SYSTEM \$117,500.00							12,132.00
	Drain system		94	\$ 1.250		Ś	117,500.00
SOIL STABILIZATION WITH POLYMER INJECTION \$1,000,000.00							117,000.00
	Soil stabilization	L.S.	1	\$ 1,000,000		ς,	1,000,000.00
PILE STRENGTHENING WITH STEEL PLATES \$335,000.00						Ψ.	.,000,000.00
TILL OTKL	GR.50 Steel bars, 2"x10"x14'-0"	ΙEΑ	56		ψ333,000.00	Ś	335,000.00
DOCK GUI	·	LA	1 30		\$10,500.00	۲	333,000.00
DOOK OO!	4" Diameter steel pipe and brackets	EA	21	\$ 500	10,000.00	\$	10,500.00
MISCELLANEOUS ITEMS \$20,000.00						, T	10,000.00
-	Environmental controls	L.S.	1	\$ 20,000.00	, 1,20000	\$	20,000.00
TOTAL						\$	1,677,441.92
	Construction Management & Inspection			6.0%		\$	100,646.52
	CONTINGINCIES			30.0%		\$	503,232.58
TOTAL CONSTRUCTION COST						\$	2,281,321.01